




	ent Location Location Desc		0955-034-004 RECOVERED OIL TO C-1100						Remaining Life (Years) Retirement Date Last Inspection Date Next Inspection Date Current Corrosion Rate			34.99 11/06/2038 08/09/2005 11/10/2013 1.43	
DP ID	MEAS METH	DP STAT	DP SZ	DT TYPE	BASE	MEAS 5	MEAS 4	MEAS 3	NEAR	LAST	MIN VALUE	CCR	REM LIFE
001.	1 UT	Α	2.00	ELL	0.140 11/96					0.140 01/04	0.100	0.00	$\infty$
001.:	2 UT	Α	2.00	ELL	0.140 11/96					0.140 01/04	0.100	0.00	$\infty$
003.	1 <b>UT</b>	Α	2.00	ELL	0.150 01/04					0.160 08/05	0.100	0.00	$\infty$
003.	2 UT	Α	2.00	ELL	0.150 01/ <b>0</b> 4					0.150 08/05	0.100	0.00	$\infty$
004.1	R RT	Α	2.00	ELL	0.160 11/96					0.150 11/03	0.100	1.43	34.99

Version: 8/13/2012 ©2009 Chevron Corporation

Content Contact: Ryan Streeter Technical Contact: Ryan Streeter Page 1 of 2 Company Confidential



## **History Brief**

For Location ID: 0955-034-004 in Unit: 0955



Report Date: August 15, 2012 Data Source: Meridium

**Brief Data:** 

Date Not Available: 1/6/2005

History Brief Date: 01/11/2005 Inspection **Event Type:** 

**Equipment ID:** Asset ID:

0955-034-004 0000110639

Work Order Nbr:

**History Type: FXD** 221

Asset Type:

Unit:

Cost Center: K.DCRRI00281 0955 - 4 CRUDE UNIT PLT 11

Headline: 5 Year VT Insp, No Issues

Reliability Analysis:

**Event Type:** 

Inspection

Cause Category: Compliance, Inspection, PM

**Effect Category:** No Effect

Repair Location:

Temporary Repair:

Save:

Date Available:

History Brief ID:

In- Service Date:

Critical:

Reference Material: Incident Event ID:

**Inspection Date:** 

Inspection Type:

EVI

Chevron - General

EI-0501118217

01/06/2005

Worked Performed By: **Program Status:** 

Maintainable Item:

Permanent Repair WO:

Name:

Inspected By:

General

**JMJG** 

**Reliability Comments:** 

Content Owner: MERCAB Last Update: August 15, 2012 © 2005 Chevron Corporation Technical Owner: Dan Buegeleisen

Page 1 of 3 Company Confidential

## **History Brief**

For Location ID: 0955-034-004 in Unit: 0955



Report Date: August 15, 2012

Data Source: Meridium

**Brief Data:** 

Date Not Available: 11/11/2003 History Brief Date: 11/12/2003 **Event Type:** Inspection 0955-034-004 **Equipment ID:** 

0000110639 Asset ID: Work Order Nbr:

**History Type:** FXD 221 Asset Type:

**Cost Center:** Unit:

K.DCRRI00281

Headline:

0955 - 4 CRUDE UNIT PLT 11

OSI Severe weld defect at TML 4-wormhole porisity with 1/2" linear defect

Reliability Analysis:

Inspection **Event Type:** 

Compliance, Inspection, PM Cause Category:

**Effect Category:** Physical Damage

Repair Location: Temporary Repair:

Save:

Worked Performed By:

**Program Status:** 

Date Available:

**History Brief ID:** 

In- Service Date:

Reference Material:

**Incident Event ID:** 

Inspection Date:

**Inspection Type:** 

Critical:

11/11/2003 VI-0311095455

11/11/2003

11/12/2003

Chevron Reliability

Pipe Wall

Maintainable Item:

Permanent Repair WO:

Name:

**LSLR LSLR** Inspected By:

Findings:

PCA ID: PCA-002031891 Inspectable: **GENERAL** 

Sub Item: Part:

**Discussion:** 

PIPE WALL

Condition:

Action: Location:

Damage Mechanism:

PCA Work Order No:

**Reliability Comments:** 

UPDATE (1-9-08):

The defective weld was removed with a spool piece from the flange above TML # 4 to the check valve just past the TML. -img

UPDATE: 11/13/03

IWO # 4CU03-4\_34-4 was written and attacthed to Passport work order # 26157596 to perform work required to repair or replace the above weld. The Al agrees with the determination that the defect does not require immediate attention. Since the actual identification of the linear defect is difficult to determine from the radiograph, it was classified as such. -img 11/13/03

Routine OSI inspection on TML 4 (2" recovered oil line to C-1100 at N18 - overflash nozzle) revealed a severe weld defect on the upper weld. Defect included a massive amount of wormhole porositiv with diameters to 1/4" as well as 1/2" linear defect running between adjacent porosity. Review of past data indicated this TML was radiographed in 1996 but no comment was made about this defect.

Field inspection showed no surface defects visible on the weld nor any indication of leakage. It appears that the welder put a heavy cover pass on the weld to coverup his poor craftsmanship. It was also determined that all of the valves around this TML were in the off position thus isolated from the main process (in this case C-1100). Though

Last Update: August 15, 2012 © 2005 Chevron Corporation

Content Owner: MERCAB

Page 2 of 3

Technical Owner: Dan Buegeleisen

Company Confidential

## **History Brief**

For Location ID: 0955-034-004 in Unit: 0955



Report Date: August 15, 2012

Data Source: Meridium

this is a significant weld defect that should have leaked because of how severe it is, it was determined there was no immediate actionable item. The results were given to the AI for final reveiw/disposition.Note: AI free to edit this HB as needed to document outcome and or make recommendation.-LRS 11-12-03.

Last Update: August 15, 2012 © 2005 Chevron Corporation

Content Owner: MERCAB

Technical Owner: Dan Buegeleisen

Page 3 of 3
Company Confidential